

Case Study

[T] +44 (0) 870 710 7560 [W] www.catalyst-commercial.co.uk/



Hospital Ground Investigation

The Challenge

The client, a hospital in the north of England required an investigation of ground conditions on one of its sites located adjacent to the main hospital.

The Solution

The site was agricultural and bordered by an “A” road to the west and a “B” road to the north. The ground investigation took place in order to provide details of subsurface ground conditions and investigate the presence of potential contamination.

The Outcome

As a result of the ground investigation, the hospital were able to install five groundwater monitoring wells. The ground investigation also helped to provide geotechnical data for an underground walkway; and to carry out Geophysical surveys to map depth to chalk and identify any potential archaeological features.



T | 0870 710 7560
W | <http://www.catalyst-commercial.co.uk/>
E | info@catalyst-commercial.co.uk